

**Work Order ID 53824**

November 19, 2009 8:49:53 AM

Page 1

Item ID: D3446-043

Accept

Setup Start

Revision ID: B

Stop

Item Name: Harness Assembly

Start Date: 11/19/09 Start Qty: 4.00

Cust Item ID:

Required Date: 11/26/09 Req'd Qty: 4.00

Customer:

Reference: Return 2009 / RA109103

Approvals:

Process Plan: \_\_\_\_\_

Date: \_\_\_\_\_

Tooling: \_\_\_\_\_

Date: \_\_\_\_\_

Run Start

QC: \_\_\_\_\_

Date: 09.11.10

SPC (Y/N): \_\_\_\_\_

Date: \_\_\_\_\_

Stop

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	----------------	--------------	--------------	---------------	---------------	------------------	----------------

Draw Nbr

Revision Nbr

D3446

Rev B

100

QC5- Inspect part completeness to step on W/O

0.00

QC

Memo

0.00

Quality Control

Original B25176. Scrap per SB08-1.

110

0.00

Purchasing

Memo

0.00

Purchasing

Return to supplier (Schroth) per NCR08-048 / SB08-1

120

QC21- Final Inspection - Work Order Release

0.00

QC

Memo

0.00

Quality Control

u 09.12.09